

CO2 Laser (SmartXide Touch) Skin Pre-Treatment Instructions

Skin Care:

- ➤ 4-6 weeks before your treatment, avoid sun exposure, as well as tanning beds and tanning creams.
- If you are tanned, you may not be treated.
- ➤ Use a broad-spectrum (UVA/UVB) sun block SPF 45 or greater when treatment area is exposed to the sun.
- > On the day of treatment, it is important that you cleanse the area to be treated.
- > If you are a man you should be clean shaven before the procedure.

Medications:

- > Depending on your skin type you may be asked to use special medications to prepare your skin for treatment.
- > If you have a history of herpes in the treatment area you may be given an antiviral.

Post-Treatment Skin Care Supplies:

- ➤ Moisturizing occlusive ointment such as:
 - Aquaphor Healing Ointment
 - Vaseline based ointment.
- ➤ Gentle, hypoallergenic skin cleanser such as:
 - Cetaphil
 - Sarna sensitive antibacterial cleanser
- > Cool gel packs
- > A broad-spectrum (UVA/UVB) sun block SPF 45 or greater for pre- and post-treatment.



General Recommendations:

- > On treatment day, you should wear comfortable clothes and a button-down shirt.
- > Do not wear any jewelry on treatment day.
- > If you wear contacts, do not wear them on treatment day; bring your eyeglasses instead.